(\*18431) Wt. 35351-J177 3m 11/46 T.S. 760

M.C.A. Form 113

## NATIONALITY AND REGISTRATION MARKS

RKS G-ALL	•
-----------	---

M.C.A. FORM 115	NATIO	NALITY AND REGISTRATION	MIWICVO
DESCRIPTION OF AIRCRAFT.	Zign Math BH82a.		FILE No. SEAD. 4159/1
toda (Historia) di Lendrigon Allonio			do
CONSTRUCTOR'S No.	582.		01.15
CERTIFICATE OF AIRWORTHINESS (if any).	No	CATEGORY	SHEET 1
CERTIFICATE OF VALIDATION (if any).	No	SUB-DIVISIONS	

	0.45		Notes the		From the Date Shown, Registration Lapsed			
	Certificate of Registration No.	Full Name and Address of Owner	Nationality of Owner	Date of Registration	Change of Ownership	Destruction or Permanent Withdrawal from Use	Cancellation by the Minister of Civil Aviation	
a law a so man eta restrictive en me	R.4159/1	Link Training Services Limited, 33 Ovington Square,	Bith	2. 10.53	14.12.53.	u a unua su reneve		notare us sure.
		London, S.W. 3.  Registered access:- 72 Finstury Pavement, London, Ed. 2	en e		Like	in EI-	AGL.	
	R.4159/2	Travelair Limited	British	11-6-58	22-7.58			
		115, Oxford Street, London W.1			-			
	R.41593	Gerence Robert William Barlow	British	25.7.50			28.8.59	
		HE8 Utbridge Road, Hayes.						
		midaleser	0.1/1					
	<i>የ</i> ፡ ዙ፣ማ}ዙ	William Henry Davenport Lowe 87 Daneby Road Catford.	British	28.8.59	9-8.60			·
		London. S.E.L.				• •		
		CONTINUED ON SHEET 2						