

CA Form 113

DESCRIPTION OF AIRCRAFT

Proctor 3

FILE No. BQ AD 1504/2

FILE No.

CONSTRUCTOR

F. Hills and Sons Limited

CONSTRUCTOR'S No.

LZ-716

SHEET 2

CONTINUED FROM SHEET 1

Certificate of Registration No.	Full Name and Address of Owner or Charterer	(1) Nationality of Owner or Charterer	Date of Registration	Termination of Charter	From the Date Shown, Registration Lapsed on Account of:-				
					(2) Whether owned or chartered	Change of Ownership	Transfer to Unqualified Owner	Destruction or Permanent Withdrawal from Use	Cancellation by the Minister of Aviation
R.1504/4	Rochester & Ulster Flying Clubs Limited The Aerodrome Rochester Kent.	(1) British	28-2-61	1-8-61	(2) owner	1.8.61			
R.1504/5	Armando Rodolfo Bini, 21, Bristlechurch Road, Ashford, Kent.	(1) British	17.8.61		(2) Owner.	10.8.62			
R.1504/6	Vendair (London) Limited, Biggin Hill Aerodrome, Biggin Hill, Kent.	(1) British	27-8-62		(2) Owners	29-5-63			
R.1504/7	Film Aviation Services Limited, Stone Court, Smallfield Road, Horley, Surrey. Registered Address: 39, High Street, Hove Crawley, Sussex.	(1) British	30-5-63		(2) Owners	8-6-63			