

CA 113

DESCRIPTION OF AIRCRAFT

Rapide DH 89A Series 4

Amended  
11/11/57  
204.

NATIONALITY AND REGISTRATION MARKS

G-AOZG

FILE No. S9.AD.5841/2

FILE No.

CONSTRUCTOR'S No.

X 7486

Certificate of Registration No.	Full Name and Address of Owner	Nationality of Owner	Date of Registration	From the Date Shown, Registration Lapsed on Account of:-		
				Change of Ownership	Destruction or Permanent Withdrawal from Use	Cancellation by the Minister of Transport and Civil Aviation
R.5841/1	Hants and Sussex Aviation Limited The Airport, Portsmouth Hants.	British	23-1-57	19.2.57.		
R.5841/2	Roy Eric Wall 3. Botby Hill House, Botby Hants.	British	11.3.57.	5.7.57.		
R.5841/3	(1) Albert Victor Boella (2) William Bogatto (1) 3 Elmfield West, Millbrook Road, Southampton (2) 9 Elmfield West, Millbrook Road, Southampton	British	22-7-57	11-11-57		
R.5841/4	West African Airways Corporation, Airways House, Ikeja Airport Lagos Nigeria	British	11-11-57	10.12.57 (Sierra Leone) W-AAC		