

G-ASAP

Certificate of Registration No.	Full Name and Address of Owner or Charterer	(1) Nationality of Owner or Charterer (2) Whether owned or chartered	Date of Registration	Termination of Charter	From the Date Shown, Registration Lapsed on Account of:-			
					Change of Ownership	Transfer to Unqualified Owner	Destruction or Permanent Withdrawal from Use	Cancellation by the Minister of Aviation
R. 7638/5	Frank Ferguson, 30, Westwood Lane, Brimington, Chesterfield, Derby.	(1) British (2) Charterer	25.3.66		10-5-66			
R. 7638/6	Anthony Bannister 664, Alum Rock Road, Alum Rock, Birmingham 8.	(1) British (2) Owner	21-6-66		1.1.67. (notified 7/2/67)			
R. 7638/7	Anthony Bannister, Leonard Sydney Cooper, 664, Alum Rock Road, Alum Rock, Birmingham, 8. 3, Plymouth Drive, Bant Green, Birmingham.	(1) British (2) Owners	9.2.67		28.6.68			
R. 7638/8	Peter Edward Constantin Brun 17, Cedar Court, Windsor, Berkshire	(1) British (2) Owner	24.7.68		31-8-69			
R. 7638/9	Orman (Carroll's Farm) Limited Leicester House, Great Massingham, Kings Lynn, Norfolk. Registered address: c/o Stanley G. Wick, Terminus Chambers, 8, Hall Lane, South Chingford, London, E4.	(1) British (2) Owners	3-9-69		26-10-69			
R. 7638/10	1) Frederick William Fay 2) William Lloyd Grose 1) Brambles, Meeting House Lane, Balcall, Birmingham, Coventry, Warwickshire. 2) Glen Cottage, Butcher Lane, Boughton, Northampton.	(1) British (2) Charterers	9-1-70		20-6-71 (confirmed 11-2-72)			

CONTINUED ON SHEET 2