

DESCRIPTION OF AIRCRAFT Vista Airtower 100

NATIONALITY AND REGISTRATION MARKS

G-ATCKFILE No. SGAD.8525/2

FILE No. _____

CONSTRUCTOR Vista Aviation Division AustraliaCONSTRUCTOR'S No. 92

Certificate of Registration No.	Full Name and address of Owner or Charterer	1) Nationality of Owner or Charterer 2) Whether owned or chartered	Date of Registration	Termination of Charter	From the Date shown, Registration Lapsed on Account of:-			
					Change of Ownership	Transfer to Unqualified Owner	Destruction or Permanent Withdrawal from Use	Cancellation by the Minister of Aviation
R.8525/1	<u>Vista (U.K.) Limited.</u> <u>134, St. Albans Road,</u> <u>Watford,</u> <u>Hertfordshire.</u> <u>Registered Address: 4, Chandos Street, Cavendish Square, London, W.1.</u>	(1) <u>British</u> (2) <u>Owner</u>	<u>5-4-65</u>		<u>10-5-65</u>			
R.8525/2	<u>George Stewart,</u> <u>4½, Chichester Road,</u> <u>Broydon,</u> <u>Surrey</u>	(1) <u>British</u> (2) <u>Owner</u>	<u>19.7.65</u>		<u>1-7-69</u>			
R.8525/3	<u>William Ernest Gunn</u> <u>Trustee of the assets of the Biggin Hill Flying Club (Loan Fund)</u> <u>6, Parkies Avenue,</u> <u>Erpington, Kent.</u> <u>14, Cowen Road,</u> <u>Chelapfield,</u> <u>Assington</u> <u>Kent</u>	(1) <u>British</u> (2) <u>Owner</u>	<u>22-7-69</u>		<u>5.3.73</u>			
R.8525/4	<u>BARRY GRAHAM HODSON</u> <u>4 GLENGAL COURT</u> <u>CODRINGTON HILL</u> <u>LONDON</u> <u>SE23 1NE</u>	(1) <u>BRITISH</u> (2) <u>OWNED</u>	<u>16.4.73</u>				<u>25.6.75.</u> <u>DESTROYED.</u>	